

Annex I: Reported Upgrades

In 2013, Equal Education conducted an audit that classified schools into three categories. “Insufficient Infrastructure” was defined as less than one toilet per 25 female students or less than one toilet plus one urinal per 40 male students, a norm detailed in the Department of Water Affairs and Forestry 2008 standards. “Dysfunctional Sanitation System” was defined as less than one working toilet per 25 female students or less than one working toilet plus one urinal per 40 male students. A “Sufficient Sanitation System” had at least one working toilet per 25 girls and at least one working toilet plus one urinal per 40 boys. However, it may still have been lacking other critical aspects (e.g. sufficient working taps).

Since the beginning of the school term, Equal Education members at high schools have been continually monitoring the delivery of sanitation improvements to schools. We have recorded the following:

	Classification in 2013 Sanitation Audit	Improvements Recorded	Outstanding Issues In Need Of Urgent Attention
Boitumelong	Insufficient Infrastructure	Initial installation of sanitation infrastructure such as urinals and toilets; Installation appears ongoing	25% of audited toilets not functioning; 42% of audited taps not functioning
Ikusasa	Sufficient Sanitation System (Toilets Only)	Additional supply of sanitary bins	13% of audited toilets not functioning; 25% of audited taps not functioning
Inqayizivele	Insufficient Infrastructure (Girls), Dysfunctional Sanitation System (Boys)	Delivery of two pre-fabricated; Some repairs to toilet seats	Pre-fabricated toilets yet fully operational; 55% of audited toilets not functioning; 40% of audited taps are not functioning
Jiyana	Not audited in 2013	Delivery of two pre-fabricated toilet blocks	Pre-fabricated toilets yet fully operational; 50% of audited toilets not functioning; 25% of audited taps not functioning
Masiqhakaze	Dysfunctional Sanitation System	Some replacement of existing toilet seats and taps; Door repairs	4% of audited toilets not functioning; 63% of audited taps not functioning
Masisebenze	Insufficient Infrastructure	Delivery of two pre-fabricated toilet blocks; Some repairs to existing toilet seats and bowls; Repairs of taps	Pre-fabricated toilets yet fully operational; 25% of audited toilets not functioning; 25% of audited taps not functioning

✉ **Postal:** PO Box 40114, Elonwabeni, 7791 🏢 **Head Office:** Washington Sqr, Capital Drive, Thembokwezi, Khayelitsha

✉ **E-mail:** info@equaleducation.org.za ~ 🌐 **Website:** www.equaleducation.org.za

📘 **Facebook:** Equal Education fan page ~ 🐦 **Twitter:** twitter.com/equal_education

☎ **Telephone:** 021 387 0022 ~ 📠 **Fax:** 0865169396

Registered S10(1)(cN) and S18A(1)(a) Public Benefit Organisation (PBO) (Exemption Number 930 027 221)

Registered Non-Profit Organisation (NPO) (Registration Number 068-288-NPO)



	Classification in 2013 Sanitation Audit	Improvements Recorded	Outstanding Issues In Need Of Urgent Attention
Phomolong	Insufficient Infrastructure	None	Needs additional sanitation infrastructure; 6% of audited toilets not functioning; 29% of audited taps not functioning
Sizwe	Insufficient Infrastructure (Girls)	None	
Tembisa High	Dysfunctional Sanitation System	Delivery of two pre-fabricated toilet blocks; Some repairs to taps and basins; Improved provision of sanitary bins	Pre-fabricated toilets yet fully operational; 41% of audited taps not functioning
Tembisa West	Insufficient Infrastructure	Delivery of two pre-fabricated toilet blocks (government provided). Upgrades of toilets and taps; Increased provision of toilet papers, soap and taps (all corporate sponsored)	Pre-fabricated toilets yet fully operational
Thuto-Ke-Maatla	Insufficient Infrastructure	Delivery of two pre-fabricated toilet blocks; Some repairs to taps	Pre-fabricated toilets yet fully operational; 13% of audited toilets not functioning; 7% of audited taps not functioning
Zitikeni	Dysfunctional Sanitation System (Girls)	Replacement of cisterns for toilets	18% of audited toilets not functioning; 13% of audited taps not functioning

